MATERIAL SAFETY DATA SHEET

lanufacturer's Name Adcoat, Inc	IAME & PRODU	CT		
		La Jolla Rd.,Placen	City, State and Zip Code tia, Calif. 92670	Emergency Phone No. (714) 630-7311
January 31, 19	75			
rade Name			Synonyms	
AC-813	Thinner		Solvents	
Section 2—II	NGREDIENTS -	TYPICAL VALUES		WT. %
Perchlore	ethylene (minin	num)	•	99
Section 3—P	HYSICAL DATA	<u>, and the state of the state o</u>		
OILING POINT ("F)		250 (121.1°C)	SOLUBILITY IN WATER 25°C	0.015g/100g
APOR PRESSURE (mm Hg at 20°C)	13	SPECIFIC GRAVITY (H2O : 1)	1.619 at 25/25°C
APOR DENSITY (air	r : 1)	5.76	% VOLATILE BY VOLUME	100 (Essentially)
PPEARANCE CO	lorless liquid.			
Section 4—F	TRE AND EXPLO	SION HAZARD DATA		
lash Point (and method used)			Flammable Limits (STP in air)—Vol. %	
None °F T.O.C., T.C.C., C.O.C.		., C.O.C.	LF.L. None	U.F.L. None
· The second state of the	respiratory equi			
Section 5—I	REACTIVITY DA	TA Conditions to svoid	omes welding area or other high tempo	erature courses which indu
Section 5—I	REACTIVITY DA	Conditions to svoid Avoid open fla thermal decom	ames, welding arcs or other high tempo	erature sources which indu
Section 5—I	REACTIVITY DA	Conditions to svoid Avoid open fla thermal decom		erature sources which indu
Section 5—I (Norr X STABLE INCOMPAT-	STABILITY mat Conditions) UNSTAI Materials to avoid	Conditions to avoid Avoid open fla thermal decom		erature sources which indu
Section 5—I (Norr X STABLE	STABILITY mail Conditions) UNSTA	Conditions to avoid Avoid open fla thermal decom	position.	erature sources which indu
Section 5—I (Norr X STABLE INCOMPAT- IBILITY Hezerdous Decomposition	STABILITY mal Conditions) UNSTAI Materials to avoid 'Yfater Other osition Products	Conditions to svoid Avoid open fla thermal decom	rrosive Oxidizing Material	erature sources which indu
Norr X STABLE INCOMPAT- IBILITY Hezerdous Decompo	STABILITY mal Conditions) UNSTAI Materials to avoid 'Yfater Other osition Products	Conditions to svoid Avoid open fla thermal decom Acid Base Con amounts of phosgene and chl	rrosive Oxidizing Material	erature sources which indu
Section 5—I (Norr X STABLE INCOMPAT- IBILITY Hazardous Decomps Hydrogen chic	STABILITY mal Conditions) UNSTAI Materials to avoid "Y/ater [Other osition Products oride and small a	Conditions to social Avoid open flathermal decom Acid Base Conditions of phosgene and children Conditions to avoid	rrosive Oxidizing Material	erature sources which indu
Section 5—I (Norr X STABLE INCOMPAT- IBILITY Hazardous Decompathydrogen chic HAZARDOUS POLYMERIZATION	STABILITY mat Conditions) UNSTAI Materials to avoid 'Y/ater Other Osition Products oride and small a HAY OCCU X WILL NOT (Conditions to svoid Avoid open flathermal decom BLE Base Conditions to svoid Athermal decom Conditions to svoid Conditions to svoid Conditions to svoid	rrosive Oxidizing Material	erature sources which indu
Norm X STABLE INCOMPATIBILITY Hezardous Decompilydrogen chic	STABILITY mat Conditions) UNSTAI Materials to avoid 'Y/ater Other Osition Products oride and small a HAY OCCU X WILL NOT (Conditions to svoid Avoid open flathermal decomes Acid Base Conditions to svoid thermal decomes Conditions to svoid Conditions to svoid Conditions to svoid COCCUR PROCEDURES—USE PROF	rrosive Oxidizing Material	erature sources which indu
Norr X STABLE INCOMPAT- IBILITY Hezerdous Decompountly drogen chick HAZARDOUS POLYMERIZATION Section 6—5 Steps to be taken in	STABILITY mal Conditions) UNSTAI Materiels to avoid "Y/eter [Other osition Products oride and small a IMAY OCCU X WILL NOT (SPILL CIR LEAK	Conditions to svoid Avoid open flathermal decomes Acid Base Conditions to svoid thermal decomes Conditions to svoid Conditions to svoid Conditions to svoid COCCUR PROCEDURES—USE PROF	rrosive Oxidizing Meterial lorine. PER PROTECTIVE EQUIPMENT	erature sources which indu
Norr X STABLE INCOMPAT- IBILITY Hezerdous Decompe Hydrogen chic HAZARDOUS POLYMERIZATION Section 6—: Steps to be taken in Small leaks: M	REACTIVITY DA' STABILITY' mal Conditions) UNSTAI Materielà to avoid 'Yfater Other Other osition Preducts oride and small a MAY OCCU X WILL NOT of SPILL CR LEAK In case material is releated.	Conditions to svoid Avoid open flathermal decomes BLE Acid Base Conditions to svoid Conditions to svoid Conditions to svoid COCCUR PROCEDURES—USE PROFessed or spilled Or soak up immediately. Re	rrosive Oxidizing Meterial lorine. PER PROTECTIVE EQUIPMENT	